

from fore ends of the holding part 220 for fitting the fixing means [30] 200 to the shadow mask

5. There are one pair of the holding parts 220 in one fixing means [300] 200 for holding the contact members 32a and 32b at opposite ends of the anti-howling means 30. This system facilitates that the contact members 32 are brought into contact with the shadow mask by elastic tension of the holding parts 220.

The following are mark-ups to show changes made to paragraph(s) starting at page 14, line 10 and ending at page 14, line 14:

The fixing means 300 includes a holding part 350 for holding the anti-howling means 30 to a required position of the shadow mask, a guiding part 320 for bringing the anti-howling means 30 into contact with the shadow mask 5, and a fitting part 310 having one side[s] of the holding part 350 and one side of the guiding part 320 connected thereto and joined to the shadow mask 5 [on the whole].

B. Clean Specification Changes

Please replace paragraph(s) starting at page 11, line 17 and ending at page 11, line 24 with the following paragraph(s):

A1 As described, there is fixing means 200 for holding and fixing anti-howling means 30 to required positions of a shadow mask 5. The fixing means 200 includes holding parts 220 for holding contact members 32 of anti-howling means 30, and fitting parts 230 extended from fore ends of the holding part 220 for fitting the fixing means 200 to the shadow mask 5. There are one pair of the holding parts 220 in one fixing means 200 for holding the contact members 32a and 32b at opposite ends of the anti-howling means 30. This system facilitates that the contact members 32 are brought into contact with the shadow mask by elastic tension of the holding parts 220.

Please replace paragraph(s) starting at page 14, line 10 and ending at page 14, line 14 with the following paragraph(s):

A2 The fixing means 300 includes a holding part 350 for holding the anti-howling means 30 to a required position of the shadow mask, a guiding part 320 for bringing the anti-howling means 30 into contact with the shadow mask 5, and a fitting part 310 having one side of the holding part 350 and one side of the guiding part 320 connected thereto and joined to the shadow mask

5.